



## GUARD TECH LAITANCES®

### Application procedure

1. Shake the product well before use.
2. Always test on a small hidden portion of the substrate before applying.
3. Use neat, do not dilute.
4. Spray the product with a low-pressure sprayer onto the dry substrate.
5. Leave the product to act for between 5-15 minutes. This time will vary depending on the thickness of laitance to be removed.
6. Rinse the entire surface, preferably with a high-pressure cleaner while brushing all the time.
7. There is no need to neutralize after rinsing.
8. Indicative coverage: 8-10m<sup>2</sup> per Kg.